


1/(a) Distributed winding refers to the way a coil side is spread between a number of slots. In three phase motors (higher powers) everything should be sinusoidal and distribution gives a more sinusoidal mmf.

(b) The main winding is in bands of 8 slots. Since the motor is single phase, the second winding is simply for starting, so does not need to be well distributed or thick wire. 8 slots means 8 steps.



$$F(\theta) = \frac{N_{eff} I}{2} \cos(\theta) \quad I(t) = \hat{I} \cos \omega t$$

$$F(\theta, t) = \frac{N_{eff} \hat{I} \cos(\omega t) \cos(\theta)}{2} \\ = \frac{N_{eff} \hat{I}}{4} [\cos(\omega t + \theta) + \cos(\omega t - \theta)]$$

1/(b) cont.


$$S = \frac{\pi^2}{\sqrt{2}} \left(\frac{d}{2}\right)^2 \cdot l \cdot \frac{\omega}{p} \times \bar{B} \times \bar{J}$$

$$= \frac{\pi^2}{\sqrt{2}} \cdot (0.025)^2 \times 0.03 \times \frac{2\pi \cdot 50}{1} \times 0.5 \times 3 \times 10^4$$

$$= 617 \text{ VA} \quad \eta = 0.8, \quad \cos \phi \approx 0.8$$

$$\Rightarrow 395 \text{ W.}$$

(c) SmCo_5 has a straight line B-H curve in the demagnetisation region. Aim for the mid point.



$$B_m = B_r/2 \quad \mu_m = \frac{B_r}{H_c}$$

$$B_m = \mu_m H_m + B_r$$

Assume infinitely permeable iron.

$$H_m l_m + H_g l_g = 0 \quad B_g A_g = B_m A_m$$

$$B_m = \mu_0 H_g \frac{A_g}{A_m} = -\mu_0 H_m \frac{l_m A_g}{l_g A_m}$$

$$B_m = B_r/2$$

$$\frac{B_r}{2} = -\frac{\mu_0}{\mu_m} \left(\frac{B_r}{2} - B_r\right) \cdot \frac{l_m A_g}{l_g A_m}$$


$$\frac{B_m - B_r}{\mu_m}$$

$$l = \frac{\mu_0 l_m A_g}{\mu_m l_g A_m} \quad \text{and minimise the airgap.}$$

24 slots, 3 phase. 8 slots per phase.

More efficient & quiet with adjustable speed but needs an inverter.

2/(a)



When commissioned as part of a variable speed drive, $V/f = \text{const}$, so $\frac{V}{\omega L_m} = \text{const}$ and smallish. Since ω is variable, the value of R_2/s should be large compared to R_1 and ωL_1 , under all conditions (i.e. we work at small $s\omega$).

Having a very low V at very low ω 's means that IR_1 becomes significant at low ω 's. This is dealt with separately by "voltage boosting", or a simple calculation.


Ignoring R_1 & ωL_1 and ωL_2

$$\omega T = \frac{3V^2}{R_2/s} \quad \bullet \quad T = \frac{3V^2}{\omega^2} \cdot \frac{s\omega}{R_2}$$

So max T means max $s\omega \Rightarrow \underline{\underline{s_{\text{rated}} \omega_{\text{rated}}}}$

$$T_{\text{max}} = \frac{3 V_{\text{rated}}^2}{\omega_{\text{rated}}^2} \cdot \frac{s_{\text{rated}} \omega_{\text{rated}}}{R_2}$$

2(a) cont.



Above base speed, the V becomes fixed.

$$I = \frac{V}{R_2/s} \quad I_{\text{rated}} = \frac{V_{\text{rated}}}{R_2/s} \text{ so } (R_2/s) \text{ is fixed. also.}$$

$$T = \frac{3V^2}{\omega^2} \cdot \frac{s\omega}{R_2} \quad (\text{i.e., } T \propto \frac{1}{\omega}) \quad s\omega = (\omega_s - \omega_r)$$

$$\frac{dT}{d\omega} = -\frac{3V^2}{\omega^3} \cdot \frac{1}{R_2} \quad \text{so as } \omega \text{ increases the slope goes down.}$$

$$2 (b) \quad T_{\omega} = \frac{3 V_1^2 \frac{R_2/s}{s}}{(R_2/s)^2 + \omega^2 L_2^2}$$

$$\text{max } T \text{ when } R_2 = s \omega L_2 \Rightarrow s \omega = \frac{R_2}{L_2}$$

$$\therefore T_{\omega} = 3 V_1^2 \cdot \frac{R_2/s}{2(R_2/s)^2} = 3 V_1^2 \frac{s}{2R_2}$$

$$4 \text{ kW} = 3 \cdot \frac{(415)^2}{\sqrt{3}^2} \cdot \frac{s}{2 \times 2.14} \Rightarrow s = 0.1$$


$$\omega = \frac{R_2}{s L_2} = \frac{2.14}{0.1 \times 6/1000\pi} = \frac{2.14 \times 1000\pi}{6} \text{ rads/sec.} \\ (178.3 \text{ Hz})$$

$$\text{noting } 0.1 \text{ slip} \quad \omega_r = 0.9 \times \frac{2.14 \times 1000\pi}{6} \\ = \underline{\underline{1008 \text{ rads/sec}}}$$

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes the need for transparency and accountability in financial reporting.

Q3/ (a) The main issue is the specific magnetic loading. This relates directly to the terminal voltage in a large machine where the leakage inductance & resistance are small. $\therefore V \propto \omega \bar{B}$ so to keep \bar{B} constant $\Rightarrow V \propto \omega$.

Over excited motor phasor diagram.




For maximum Torque per amp.

$$T \omega_s = 3 V I \cos \phi$$

$$T = \frac{3 V}{\omega_s} I \cos \phi \quad \therefore \cos \phi = 1 \quad \text{ie. unity power factor}$$

eg.



so E must be adjusted.

$$E = \sqrt{V^2 + I^2 \omega^2 L_s^2}$$


3
(6)

2.7 MW Ratings.

1250 V, 1400 A. 2.7 mH. 48 Hz. 2.7 MW

0.9 pf leading.

Excitation at full load. upf.




$$\frac{2.7 \text{ M}}{1250\sqrt{3}} = I = 1247 \text{ A.}$$

48 Hz 2.7 mH


$$\Rightarrow 2.7 \text{ m} \times 2\pi \times 48 = 0.814 \text{ j}\Omega.$$

~~Same speed~~ Half speed ~~Full~~



~~1/8 Torque~~

~~1/25~~
80% speed
50% Torque.



$$E' = 706 \text{ V}$$


$$\sqrt{3} \times 0.8 \text{ V} \times I = \sqrt{3} \text{ V} \times 1247 \times 0.5 \times 0.8$$

$$I = 1247 \times 0.5 = 624 \text{ A}$$


3 (c) A P.M. solution could offer a more efficient drive, with no rotor excitation. A gearbox means that a motor speed which is high may be used, making the motor much smaller.

A sinusoidal scheme has smooth torque and no vibrations. The control electronics can be a simple inverter. The trapezoidal scheme needs fast changing currents ~ not easy on big motors.

4 (a) 2 stack 2 phase




Internal magnet, axially aligned.
Teeth on the rotor and on the stator poles.
2 sets of windings.




(4 steps gives one tooth pitch rotation.)
2 phase excitation moves the peak & increases the torque. Peak moves $\frac{1}{8}$ of a tooth pitch, because the other phase gives a curve $\frac{1}{4}$ pitch away

4 (c)



The torque maybe calculated using reluctance & energy stored in the gap.



$\therefore \hat{T}$ when $\delta = 90^\circ$

$E \propto \omega$ due to the permanent magnets.

$$\hat{T} = \frac{1}{\omega_s} \cdot V \cdot \frac{k\omega}{\omega L_s} = \frac{1}{\omega_s} \cdot \frac{V k}{L_s}$$

$$\hat{T} \propto \frac{1}{\omega_s}$$

