

1/ a) Specific Magnetic Loading - Average flux density over one pole pitch. Other flux densities in the machine can be found from this.

Specific Electrical Loading - Total effective current averaged around the airgap. It is not current density. Current density is applied to give the final wire choice and the depth of the slots (and winding losses).

b/ Using Specific Magnetic Loading  $\bar{B}$  and Specific Electrical Loading  $\bar{J}$

$$S = 3 V_{ph} I_{ph} = \frac{\pi}{\sqrt{2}} \text{Vol.} \frac{\omega}{p} \bar{B} \bar{J}$$

Assume 80% efficiency, 0.8 power factor.

$$6000 \text{ rpm} \equiv 200\pi \text{ rads/s}$$

$$\frac{50 \text{ kW}}{0.8 \times 0.8} = \frac{\pi}{\sqrt{2}} \text{Vol.} \cdot 200\pi \times 0.5 \times 30,000$$

$$\text{Vol} = 3.73 \times 10^{-3} \text{ m}^3 \text{ (3.73 L)}$$

Could be wheel shaped or bottle shaped!

16 cont./

A gearbox allows for a higher motor speed and motor volume can be reduced.

Higher motor speeds may increase iron losses. (or inverter losses, or cost of gearbox)  
(any one point)

2 pole motors have long end windings.

8 pole motors at 6000rpm means 400Hz ac, which is OK with more expensive laminations, more complicated winding, more cost (any 2 points).

8 pole, distribute by 2 slots, 3 phases = 48 slots.

Single layer to keep costs (and maths!) low

Ignore  $R_1$  &  $j\omega L_1$  so,

$$V = E = \ell \frac{\omega}{p} \cdot d \cdot N_{\text{eff}} B_{\text{rms}} \quad B_{\text{rms}} = \frac{\bar{B} \pi}{2\sqrt{2}}$$

$$k_d = \frac{\sin(2\beta p/2)}{2 \sin(\beta p/2)} \quad \beta = \frac{360}{48} = 7.5^\circ \quad k_d = 0.866$$

$\Delta$  connected (thinner wire, more turns) or star.

$$200 = \frac{3.73 \times 10^{-3}}{\pi \cdot 0.12^2} \times 200\pi \times 0.240 \times N \times 0.866 \times 0.5 \times \frac{\pi}{2\sqrt{2}}$$

$$N = 33.6 \quad (\text{Not integer} \times 16)$$

Choose 32 Turns

1b cont.

This is only ~~#~~ 2 turns per slot. The current is high, so parallel paths maybe necessary. ( $\Delta$  winding)


$$I_{ph} = \frac{50k}{0.8 \times 0.8} \cdot \frac{1}{3 \times 200} = 130A$$

$$5A/mm^2 \Rightarrow 26mm^2 = \pi \left(\frac{d}{2}\right)^2 \Rightarrow d = 5.7mm$$

$$2 \text{ paths} \Rightarrow 13mm^2 \Rightarrow d = 4mm. \text{ Better.}$$

Some optimization needed!

2 a/



At speed  $T\omega_s = 3I_2^2 R_2/s$ .

Neglect  $R_1$  &  $j\omega L_1$

$$T = \frac{3}{\omega_s} \cdot \frac{V^2 R_2/s}{(R_2/s)^2 + (\omega L_2)^2}$$


$$\omega_s = \frac{\omega}{p}$$

$$= 3 \left( \frac{V^2}{\omega^2} \right) \cdot \frac{R_2 s \omega}{R_2^2 + (s\omega L_2)^2} \quad 4$$

If we keep  $\frac{V}{\omega}$  constant  $T$  is independent of  $\omega_s$ .

At standstill,  $s = 1$  so  $s\omega = \omega$  so a small  $\omega_s$  provides the full torque. 2

Sketched



2(b) Neglect  $s\omega L_2$   $\omega_s = \frac{\omega}{p}$

$$T = \frac{3pV^2}{\omega^2} = \frac{s\omega}{R_2}$$

$$k = \frac{V}{\omega_s}$$

A constant value keeps  $I_m$  constant (flux constant)

$$= 3p k^2 \frac{s\omega}{R_2} = 3p k_m^2 \frac{s\omega}{2}$$

$$P_{in} - P_{out} = T\omega_s - T\omega_r \quad s\omega_s = \omega_s - \omega_r$$

$$= T s\omega_s = \frac{T s\omega}{p} \quad \text{--- ①}$$

$$= 3K_m^2 (s\omega_s)^2$$

$$\sqrt{P_{in} - P_{out}} = \sqrt{3} K_m s\omega_s \quad \text{Oops!}$$

Substitute for  $s\omega$  in ①


$$P_{in} - P_{out} = \frac{T^2}{3pK_m^2}$$

$$K_m^2 = \frac{T^2/p^2}{3(P_{in} - P_{out})}$$

$$K_m = \frac{T/p}{\sqrt{3(P_{in} - P_{out})}}$$

This neglects  $R_1$  &  $j\omega L_1$  and assumes full flux in the machine.

2/c) Equivalent ckt for standstill, rated flux



2 pole, 3000rpm.

$$s_{\text{rated}} = \frac{60}{3000} = 0.02$$

@ 50Hz

$$T = 3k^2 \frac{s\omega}{R_2} = \frac{3700}{2\pi 50 \times 0.98} = \frac{3 \times 4.15^2}{(2\pi 50)^2} \cdot \frac{0.02 \times 2\pi 50}{R_2}$$

$$R_2 = \frac{3 \cdot 4.15^2 \cdot 0.02 \times 0.98}{3700} = 2.74 \Omega$$

$$I_2 = \frac{4.15}{2.74/0.02} = 3.03 \text{ A} \quad \text{p.f.} = 0.8 \quad (3-4-5 \text{ triangle})$$

$$\Rightarrow I_m = \frac{3.03 \times 3}{4} = 2.27$$

Need to estimate  $V_{\text{boost}}$  at standstill.

$I_2$  &  $I_m$  remain the same.

$s = 1$  BUT  $s\omega$  is the same as above.

$$\Rightarrow s\omega = 0.02 \times 2\pi 50 = 2\pi \text{ rads/s (1Hz)}$$


$$\therefore V \text{ with no boost is } \frac{4.15 \times 2\pi}{2\pi 50} = 8.3 \text{ V.}$$

We don't know  $R_1$ . If we did we could be precise, but usually  $V_{\text{boost}}$  is commissioned in a simple manner. And  $R_1 \approx R_2$  (referred)


Say 16.6V, 1Hz

i.e. Choose something sensible  
8.3V, 1Hz has no boost

3 a / Must have  $\theta$  &  $\omega$  feedback.<sup>2</sup>  
 Also needs current feedback



Phasor diagram.



this is the same as for a synchronous motor  
 except the controller maintains the Torque angle  
 $\beta$  at  $90^\circ$ . Everything is sinusoidal.


At speed  $R$  can be neglected.<sup>2</sup>

$$E \propto k\phi\omega.$$

$$T\omega = VI\cos\phi = VI\cos\delta = I V\cos\delta = IE$$

Cogging is a reluctance torque, which  
 would mean the torque has a ripple, which  
 becomes a ripple in the finished work.<sup>2</sup>


3/b) As speed increases:



Power =  $EI$   $E \sin \beta$  -  $I$  decreases.

Until the  $E \approx V$  then it's stuck.


the only alternative to allow  $\beta$  to change.



"Phase advance" is angle  $\delta$ . This is just the same as for an overexcited synchronous motor.




3/ b) cont.



$$300^2 = 65n^2 + 16.5^2 n^2$$

$$n = 4.474 \quad \underline{4474 \text{ rpm}}$$

30° advance.



$$300^2 = 56.75^2 n^2 + 14.3^2 n^2$$


$$n = 5.126 \quad \underline{5126 \text{ rpm}}$$

4 a/ Microstepping is based on exciting the windings of a 2 phase motor at the same time, with fractional current to get a step position between two steps<sup>2</sup>. This has two <sup>main</sup> uses. Firstly it can be used to move between <sup>major</sup> steps without exciting oscillations and it can provide more accurate positioning.<sup>2</sup>

The half or full step modes are symmetrical and magnetic saturation doesn't matter.<sup>2</sup>  
An asymmetrical or in-between mode has problems with saturation of the corners of the teeth etc. so the position is not likely to be as accurate. In all cases the load affects the position, so with a known load the resultant position can be repeated accurately even using microstepping.<sup>2</sup>

4 b/

12:14



With  $A$  on in the right sense, pole 1 will align (and  $\bar{A}$  misalign) with ~~4 & 5~~ 5.

When  $\bar{B}$  comes on next, pole 2 will align (and  $B$  misalign with 5 & 6)

When  $C$  comes on next, pole 3 will align. (and  $\bar{C}$  misalign with 6 & 7) 2

And so on. (The misalignment is important with a "salient" or concentrated stator winding on simple poles. If it were 6:6 stator to rotor the cogging or reluctance torque would be massive.

(Clear detent positions arise here, but no great detent torque.)

Step angle. Flux move  $30^\circ$  but rotor moves? (In brushless dc it is half stepping.)  $\frac{180^\circ}{7} = 25.7^\circ$   
 $\underline{\underline{4.3^\circ}}$  2  
 $\bar{A}\bar{B}, \bar{B}\bar{C}, \bar{C}\bar{A} \dots$

4(c) / 100kW, 3000rpm.

	DC	Induction	BLDC	SR
Eff.	4	4	6	5
Maturity	6	6	5	4
Cost <sup>Low</sup>	4	6	3	6
Noise	6	5	4	0
<hr/>				
	20	21	18	15

The induction motor has few drawbacks and can be made to be quite efficient. At these powers water cooling is probably a good idea, lessening the drawback of efficiency. <sup>2</sup>

In a different application a heavy weighting may be applied.