

3B4 CRIB 2011

1 a) Several ways. Force p.u. area of the surface of the rotor is $\vec{J} \times \vec{B}$ (left hand rule!). \vec{B} reverses at the poles, N-S-N-S etc, and in any sensible motor \vec{J} also reverses under the poles, giving the total force.² \therefore pole number does not affect the design. QED Proving this by volume is not necessary as say 4 & 6 pole can be compared. See below for gearboxes.


OR.

$$S = \frac{\pi}{\sqrt{2}} \cdot \pi \left(\frac{d}{2}\right)^2 l \frac{\omega}{p} \cdot \overline{B} \cdot \overline{J} \quad 2$$

where ω is the frequency and p pole pairs. $\frac{\omega}{p}$ is the base speed. So for same speed $\omega \propto p$.² Here more speed means more power hence wide use of gearboxes since smaller motor for a given power.

(Above $\vec{J} \times \vec{B}$ is force; faster rotation all else the same means more power hence use of gearboxes. (\vec{J} & \vec{B} are constraints))'

1b



$$S = \frac{\pi}{\sqrt{2}} \times \pi \left(\frac{d}{2}\right)^2 l \cdot \frac{\omega}{P} \bar{B} \bar{J}$$

$$= \frac{\pi}{\sqrt{2}} \times \pi \left(\frac{0.03}{2}\right)^2 \times 0.125 \times \frac{100,000}{60} \times 2\pi \cdot 0.5 \times 30,000$$

$$= 30.8 \text{ kVA}$$


4

$$P = S \times 0.8 \times 0.8 \approx 19.7 \text{ kW}$$

$$\frac{100,000}{60} = 1600 \text{ Hz} \quad 3300 \text{ Hz for 4 pole.}$$

- any 3
- 1) Long & small diameter so endwinding is small part. ^{so small losses} High frequency goes higher, still of 4 or 6 pole is used, its less of an issue
 - 2) Low inertia, so can accelerate the turbo really fast ~ needs around 0.1 sec!
 - 3) i) Keeping magnets glued on is easier.
ii) Unbalanced load on bearings is less/easier to manage.
iii) Short flux path in iron parts
- 1 (any one)

1b cont. 2 pole 3 phase. star. ($p=1$)



$$\frac{2470}{\sqrt{3}} = 1426V$$

$$I = 15A.$$

$$5A/mm^2$$

Lets distribute by 3 ~ assume $k_d \approx 1$

$$1428 = l w d N_{eff} B_{rms} \quad B_{rms} = \frac{\pi \bar{B}}{2\sqrt{2}}$$

$$1428 = 0.125 \times 2\pi \cdot \frac{100,000}{60} \times 0.044 \times \frac{\pi 0.5}{2\sqrt{2}} N_{eff}$$

$$N_{eff} = 44.6 \Rightarrow 45 \text{ turns } (3 \times 15)$$

$$\frac{15}{5} = 3 \text{ mm}^2 ; 15 \text{ turns } 45 \text{ mm}^2 \text{ per slot}$$

18 slots. Assume a fill factor of 0.6

$$L \pi d \cdot \frac{20}{360} = 7.7 \text{ mm. Say } 4 \text{ mm wide slot}$$

$$\frac{45 \text{ mm}^2}{0.6 \times 4 \text{ mm}} = 18.75 \text{ mm.}$$


$$\text{Core} - \hat{B}_c y = \frac{1}{2} \pi \frac{d}{2} \bar{B} \quad \text{keep losses down} \sim \hat{B}_c = 1T$$

$$y = \frac{1}{2} \pi \frac{0.044}{2} \cdot 0.5 = 0.0173$$

$$\text{Diameter } 0.044 + 2 \times 0.0173 + 2 \times 0.0187 = 0.116$$

Iterate with distribution by 2 ~ maybe easier to make!
116 mm


2 a) Big phasor diagram.



V_2 is orthogonal to the flux vector.
Magnitude $\propto \hat{B} \omega$.

Clearly power is $T \omega_s = V_2 I_2 \cos \phi$.

$$V \propto \phi \omega \quad V_2 = k \phi \omega_2$$




$$T = \frac{V_2 \cdot I_2 \cos \phi}{\omega_s}$$

$$T = k \phi I_2 \cos \phi \quad 2$$

The mechanical arrangement of the coils gives position to the voltage, current and flux, which also have magnitudes. Vector sum of the three phase windings vectors produces a single vector for each, which rotates in space.

2 a cont/ Neglect R_1 , $j\omega L_1$ and $j\omega L_2$ at full flux



$$\frac{T\omega}{P} = 3I_2^2 \frac{R_2}{s}$$

$$T = 3P \left(\frac{V_1^2}{\omega^2} \right) \frac{s\omega}{R_2}$$

$k\phi$ as above.

In steady state $\frac{V_1}{\omega L_m}$ is constant. In a transient



V_1 can rise but the current producing the flux I_m cannot change much as L_m is large.

So a sharp change in V_1 and ω (and s) will produce much more I_2 and torque independently of the flux.* Treating s as a transient quantity means that the angle of V_1 with respect to the flux will be calculated correctly (Vector control)

* After a while it settles down with the right

flux as $\frac{V}{\omega} = \text{const}$

2 b/ neglecting stator terms



@ 100 Hz 353V pf 0.96 $\frac{100 \text{ kW}}{3}$

$$\frac{100 \text{ kW}}{3} \left(\frac{1}{1-0.02} \right) = I_2^2 R_2 / 0.02$$

$$\frac{100 \text{ kW}}{3} \left(\frac{1}{1-0.02} \right) = V_1 I_2 \cos \phi$$

$$I_2 = \frac{100 \text{ k}}{3} \cdot \frac{1}{353} \cdot \frac{1}{0.96} = 98.36 \text{ A}$$

$$R_2 = 0.07$$

@ 150 Hz: $T = 3 \frac{V^2}{\omega^2} \cdot \frac{s}{R_2}$, req. ωL_2 ; V_2 at max 353V
 $\Rightarrow T \propto \frac{1}{\omega}$ "const power"

Inverter & motor current at max 98.36A.

so for same power R_2/s is const $\therefore s = 0.02$ (Rated)

But check p.f.

@ 100 Hz $\phi = \cos^{-1} 0.96 = 16.2^\circ$


@ 150 Hz $\phi_2 \approx 16.2^\circ \times 1.5$


$\therefore \cos \phi_2 = 0.91$

max power = $353 \times 3 \times 98.36 \times 0.91 = 95 \text{ kW}$

Good enough probably!

so $s \approx 0.02$






Trapezoidal means a simple pattern of switching, with current control on the inner loop to set the torque. *



Starting is tricky as there is no synchronisation. But the motor is a synchronous motor so can run open loop. So a pattern and frequency is applied, with a good magnitude of current so the rotor will move. 2

* At speed, the current is applied at the correct angles. 2




and so on for 3 phases.

3 b/




I in phase with E is the key element of BLDC shown as a phasor diagram for Sine BLDC or in trapezoidal/quasi for trap. BLDC above. 2

3c / Series resistance must be included.




Voltage controlled so $V \propto \omega$ and angle of V adjusted w.r.t. I to keep it brushless.

Hard to draw as the 'new' condition depends on the load! BUT more torque means more I as fixed flux (PM motor), which means more voltage IR , so E drops by ω dropping, so V drops and so on until a new "load condition" is found. Fine for a propellor load!



OR /

eg.
compare
above




any
fair
attempt!

(Recall lecture demo!)

4 a/ Stepper drives are open loop, although there may be some check on a microswitch. With the torque depending on position, it is possible to excite resonances related to the torque/current relationship with θ and the inertia $J\ddot{\theta}$. If the load does not vary, a combination of step rates and acceleration can be found which works, avoiding pullout. 4



By continuing a steady acceleration a fixed torque is required $T_e = J\ddot{\theta}$, which means the teeth are never aligned, so oscillation cannot start. 2



$\rightarrow \frac{6000}{400} \times 2\pi \text{ rads/sec} = \omega'$
($\div 10$ at the load.)

$\frac{1}{T} \left(1 - \frac{\omega}{\omega'}\right) = J \dot{\omega}$

$J_L = \frac{0.002}{10^2} = 2 \times 10^{-5}$


$J \dot{\omega} + 0.63 \frac{\omega}{\omega'} = 0.77$

add to motor
 $J = 3 \times 10^{-5}$

at the motor

$\frac{d\omega}{dt} + \frac{0.63}{J\omega'} \cdot \omega = \frac{0.77}{J}$

$\tau = \frac{\omega' J}{0.63}$



$\tau = \frac{30\pi \times 3 \times 10^{-5}}{0.63}$

$\tau = 4.49 \text{ ms}$

But we have no data beyond 6000 $\frac{1}{2}$ s/s.

So max acc to 6000 $\frac{1}{2}$ s/s.

$(1 - e^{-t/\tau}) = \frac{6000}{7333}$

$\frac{t}{\tau} = 1.70$

$t = 7.65 \text{ ms}$

profile as shown.

4 b cont

We need 2.5 revolutions, or $1000 \frac{1}{2}$ steps

$$\int_0^{t'} 7333 (1 - e^{-t/\tau}) dt = 500 \quad (\text{ok if less than } 7.67 \text{ ms})$$


better, how many steps to $6000 \frac{1}{2}$ /s.?

$$\begin{aligned} \int_0^{\tau} 7333 (1 - e^{-t/\tau}) dt &= 7333 (t + \tau e^{-t/\tau}) \Big|_0^{\tau \times 1.7} \\ &= 7333 (\cancel{\tau} + \tau e^{-1.7} - \cancel{\tau}) \\ &= 23 + 6 = 29 \end{aligned}$$

leaves $1000 - 2 \times 29 = 942 \frac{1}{2}$ steps at $6000 \frac{1}{2}$ /sec.

$$\begin{aligned} \text{total} & \quad \text{ms} + 2 \times 7.65 \text{ ms} \\ 157 & \\ & = \underline{\underline{172.3 \text{ ms}}} \end{aligned}$$

A lower gear ratio could speed it up.



Slower to max speed, but higher max speed!